

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/10/2018

Submitted Date:

05/10/2018

Document Number:

677900313

FIELD INSPECTION FORM

Loc ID 321195 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10626
Name of Operator: DOVER ATWOOD CORPORATION
Address: 1875 HARSH AVENUE SE
City: MASSILLON State: OH Zip: 44646

Findings:

- 13 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Levengood, John	(330) 809-0630	jlevengood07@gmail.com	
Crane, Rocky	(719) 529-0682	rockycrane@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
294471	WELL	PR	01/01/2017	GW	009-06649	WEBSTER 1-3	PR

General Comment:

[Routine Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Trail through farm ground		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	Lease sign by county road at water tanks. Update to current operator		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Stencils on tanks. Add NFPA label		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	<input style="width: 500px; height: 20px;" type="text"/>	
Corrective Action:	<input style="width: 500px; height: 20px;" type="text"/>	Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	Arrow gas engine		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Meter run 1750' northeast of wellhead on west side of county road		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator by water tanks		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Dansco unit		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		

Comment: Gas scrubber		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	FIBERGLASS AST		37.294530,-102.240750
Comment: 2-50bbls fiberglass water tanks 1750' northeast of wellhead					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	50bbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 294471 Type: WELL API Number: 009-06649 Status: PR Insp. Status: PR

Producing Well

Comment: Valves at wellhead are open. Down stream valves at meter shed are shut in

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Other	Pass			

Comment: [Access is farmed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT