

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/10/2018

Submitted Date:

05/11/2018

Document Number:

688301821**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 317186 Sherman, Susan 2A Doc Num: _____

Operator Information:OGCC Operator Number: 24320Name of Operator: DIAMOND OPERATING, INC.Address: 6666 GUNPARK DR STE #200City: BOULDER State: CO Zip: 80301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Young, Rob		rob.young@state.co.us	
Peterson, Dave	(303) 494-4420	davep@flatironenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
237070	WELL	PR	01/16/2012	OW	121-09571	GULLEY 1	PR

General Comment:

Flowline leak, Form 19I, #401635835 was submitted. Wheat field cleanup and soil stockpiled at tank battery (see attached photos).
 Flowline fixed and well producing.

Inspected FacilitiesFacility ID: 237070 Type: WELL API Number: 121-09571 Status: PR Insp. Status: PR**Completion**

Operation:

Date Flowback:

Contractor:

Comment:

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688301822	Diamond Gulley 1 Flowline leak	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4460358