

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/08/2018

Submitted Date:

05/15/2018

Document Number:

690100522**FIELD INSPECTION FORM**
 Loc ID 413517 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@anadarko.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412063	WELL	SI	01/01/2017	GW	123-30372	ADLER 10-33	EG
412064	WELL	TA	06/01/2017	OW	123-30373	ADLER 20-33	EG
412065	WELL	TA	06/01/2017	OW	123-30374	ADLER 15-33	EG
412066	WELL	TA	06/01/2017	OW	123-30375	ADLER 9-33	EG
412067	WELL	SI	01/01/2017	OW	123-30376	ADLER 16-33	EG
412393	WELL	TA	06/01/2017	OW	123-30439	ADLER 33-34	EG
412394	WELL	SI	01/01/2017	OW	123-30450	ADLER 38-33	EG

General Comment:

COGCC Inspector met with the Anadarko LOE Construction Supervisor (Tyler Price) on site. The wells on location ID #413517 have been plugged and abandoned. The facility/ tank battery is in the process of being decommissioned (tanks and equipment scheduled for removal). Photo's uploaded can be accessed via links at end of report.

Inspected Facilities

Facility ID: <u>412063</u>	Type: <u>WELL</u>	API Number: <u>123-30372</u>	Status: <u>SI</u>	Insp. Status: <u>EG</u>
Facility ID: <u>412064</u>	Type: <u>WELL</u>	API Number: <u>123-30373</u>	Status: <u>TA</u>	Insp. Status: <u>EG</u>
Facility ID: <u>412065</u>	Type: <u>WELL</u>	API Number: <u>123-30374</u>	Status: <u>TA</u>	Insp. Status: <u>EG</u>
Facility ID: <u>412066</u>	Type: <u>WELL</u>	API Number: <u>123-30375</u>	Status: <u>TA</u>	Insp. Status: <u>EG</u>
Facility ID: <u>412067</u>	Type: <u>WELL</u>	API Number: <u>123-30376</u>	Status: <u>SI</u>	Insp. Status: <u>EG</u>
Facility ID: <u>412393</u>	Type: <u>WELL</u>	API Number: <u>123-30439</u>	Status: <u>TA</u>	Insp. Status: <u>EG</u>
Facility ID: <u>412394</u>	Type: <u>WELL</u>	API Number: <u>123-30450</u>	Status: <u>SI</u>	Insp. Status: <u>EG</u>

Flowline

#1	Type:	of Lines
<u>Flowline Description</u>		
Flowline Type:	Size:	Material:
Variance:	Age:	Contents:
<u>Integrity Summary</u>		
Failures:	Spills:	Repairs Made:
Coatings:	H2S:	Cathodic Protection:
<u>Pressure Testing</u>		
Witnessed:	Test Result:	Charted:
<u>COGCC Rules(check all that apply)</u>		
<input type="checkbox"/> 1101. Installation and Reclamation <input type="checkbox"/> 1102. Operations, Maintenance, and Repair <input checked="" type="checkbox"/> 1103. Abandonment		
Comment:	The flowlines routed to this facility from the well pad (Location ID #413517) have been disconnected, flushed and bullplugged/ capped. The offsite wellhead flowlines are marked on surface (with pin flags) and scheduled to be removed. Also, all flowlines at the facility (dump lines, process pipe) are scheduled to be removed.	
Corrective Action:		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100529	Facility in process of being discomissioned	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4463862
690100530	View west toward well pad (backhoe/ wells PA'd)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4463863