



**Location**

Overall Good:

**Signs/Marker:**

Type WELLHEAD

Comment: \*3

Corrective Action:

Date:

**Emergency Contact Number:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type OTHER

Comment: Stained soil at 70 Ranch Laura 24-20

Corrective Action: Comply with rule 603.f. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 06/11/2018

Overall Good:

**Spills:**

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type WELLHEAD

Comment: agricultural \*3

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Plunger Lift

# 3

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		

Comment: refer to locid#332409

Corrective Action:

Date:

**Paint**

Condition

Other (Content)

Other (Capacity)

Other (Type)

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

<b>Venting:</b>				
Yes/No	NO			
Comment:				
Corrective Action:				Date:

<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 272904 Type: WELL API Number: 123-22288 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI. Last produced Oct 2017.

Corrective Action:  Date:

**BradenHead**

Comment: Bradenhead plumbed to surface.

Corrective Action:  Date:

Facility ID: 272938 Type: WELL API Number: 123-22292 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI. Last produced Oct 2017.

Corrective Action:  Date:

**BradenHead**

Comment: Bradenhead plumbed to surface.

Corrective Action:  Date:

Facility ID: 285743 Type: WELL API Number: 123-24031 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI. Last produced Oct 2017.

Corrective Action:  Date:

**BradenHead**

Comment: Bradenhead plumbed to surface.

Corrective Action:  Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401635368	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4458394">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4458394</a>
684905382	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4458387">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4458387</a>