

# Construction and Stormwater Inspection

May 14, 2018

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 454492

Inspection Document #: 682403570

Weld County, CO

SWSE Section 18 T4N R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Enright /18-N  
Location ID: 454492



**Photo 1.** Photo taken from the entrance of location, facing North. Operator has installed tracking device BMPs. Based off the location file, Operator is not using the proposed access road. This access road is east of the proposed access road.



**Photo 2.** Photo taken from the entrance of location, facing East. Ditch and berm BMP has been installed around the entire perimeter of the location. Portions of the berm BMP are unconsolidated. An unconsolidated berm is not a proper functioning BMP.

Inspection Photos  
Location Name: Enright /18-N  
Location ID: 454492



**Photo 3.** Photo taken from the southeast perimeter of the location, facing North. See comments under Photo 2.



**Photo 4.** Photo taken from the northeast perimeter of the location, facing North. Ditch BMP has been filled in from construction operations and needs maintenance. Topsoil has been stockpiled and temporarily stabilized with equipment tracking along the eastern perimeter of the location.

Inspection Photos  
Location Name: Enright /18-N  
Location ID: 454492



**Photo 5.** Photo taken from the northeast perimeter of the location, facing West. Photo illustrates a portion of the unconsolidated berm BMP and ditch BMP that need maintenance.



**Photo 6.** Photo taken from the northwest perimeter of the location, facing North. See comments under Photo 5.

Inspection Photos  
Location Name: Enright /18-N  
Location ID: 454492



**Photo 7.** Photo taken from the southwest perimeter of the location, facing East. See comments under Photo 2.



**Photo 8.** Photo taken from the proposed access road area, facing North. The proposed access road has been flagged and appears some traffic used this area, but this is not the current access road being used- see Photo 1.