



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern portion of the project area from the northeastern corner of the working area facing westward. Revegetation is progressing with grazed grasses such as western wheatgrass (*Pascopyrum smithii*).



Photo 3. View of the eastern portion of the project area from the northeastern corner of the working area facing southward.



Photo 4. View of the southern portion of the project area from the southeastern corner facing westward. No significant erosion observed; however, this area needs to be carefully monitored or more robust stormwater controls installed.



Photo 2. View of the eastern portion of the project area from the northeastern edge facing southward. Vegetation on flat, graveled portion of the well pad is dense Russian thistle (*Salsola tragus*).



Photo 3. View of the western portion of the project area from the northeastern edge facing southwestward.



Photo 4. View of the northern cut-slope facing westward from northern edge.