

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/15/2018

Submitted Date:

05/16/2018

Document Number:

691300198

FIELD INSPECTION FORM

Loc ID 335662 Inspector Name: Kraich, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 1801 CALIFORNIA STREET #2500
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Kraich, Adam	970-420-0536	Adam.Kraich@state.co.us	(Area 117) Field Operations
,		Cogcc.inspections@crestonepr.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292091	WELL	SI	11/01/2017	OW	123-26238	SOSA 22-18	SI

General Comment:

(This area is currently blank for general comments.)

Inspected Facilities

Facility ID: 292091 Type: WELL API Number: 123-26238 Status: SI Insp. Status: SI

Complaint

Comment: [Inspection in response to complaint.](#)

Field Inspector Assigned: Adam Kraich

Complaint Received:

Date: 5/15/2018

Complaint Contacted:

Date: 5/15/2018 Time 13:41

Location #: 335662

Inspection Document #: 691300198

Nature of complaint: Noise

Field Inspector Actions:

On 5/15/2018, I received a complaint in regards to construction sounds around the area of 415 Evans St. in Erie CO.

On 5/5/2018, I contacted the complainant via phone call, He informed me there was some sort of construction taking place behind his residence.

On 5/15/2018, I visited the Sosa 12-18 location, owned and operated by Crestone Peak Resources. I discovered the wells on the location are in process of being plugged and abandon. The operator does have sound walls put up on the southeast edge of location (towards the complainants address). I informed rig management of the complaint, they admitted the reverse alarms on their front end loader was loud. Rig management offered to change their process to move the front end loader only in a forward direction, and only in reverse if absolutely necessary.

No violation of COGCC rules were observed at the time of the inspection.

All information reviewed and site inspection information were submitted to the complaint specialist for further review.

Corrective Action:

Date:

Workover

Comment: [Rigging up workover unit for plug and abandonment.](#)

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691300199	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4464947