

Interim Reclamation Inspection

May 14, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP- #47120

Location ID: 159823

Inspection Document #: 682403582

Weld County, CO

SESE Section 26 T4N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: WILSON RANCH /34N-
27HZ
Location ID: 159823



Photo 1. Photo taken of the eastern battery location, facing South. Appears the Operator has performed interim reclamation activities to reduce disturbance areas only needed for production operations, with the evidence of drilling rows and straw crimped mulch. Germination was apparent throughout the interim areas. Operator shall continue to monitor and manage this site until the location meets Rule 1003 standards. Rill erosion was observed along the eastern location- red circle.



Photo 2. Photo taken of the northeastern battery location, facing West. See comments under Photo 1. In addition, Kochia rosettes were also observed throughout interim areas.

Inspection Photos
Location Name: WILSON RANCH /34N-
27HZ
Location ID: 159823



Photo 3. Photo taken of the northwest battery location, facing South. See comments under Photo 1 and 2.



Photo 4. Photo taken of the eastern well location, facing North- see comments under Photo 6.

Inspection Photos
Location Name: WILSON RANCH /34N-
27HZ
Location ID: 159823



Photo 5. Photo taken of the northwest well location, facing South. See comments under Photo 1 and 2.



Photo 6. Photo taken of the northeast well location, facing South. Appears portions of the eastern well location are not needed for production operations. Operator shall comply with Rule 1003 standards if these areas are no longer needed.