

Inspection Photos

05/15/2018

Operator: WIEPKING-FULLERTON ENERGY LLC -
96340

Location ID: 321883

Inspection Doc. Number: 682503357
Cheyenne County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: WIEPKING-FULLERTON ENERGY LLC - 96340
Location ID: 321883



Photo 1: Photo taken from the east end of the location, facing east. Photo shows section of the access road NOT included in the variance request appears to have had reclamation work conducted.



Photo 2: Photo taken from the southeast end of the location, facing west. Photo shows overview of the location. Recent reclamation work evident.

Inspection Photos

Operator: WIEPKING-FULLERTON ENERGY LLC - 96340

Location ID: 321883



Photo 3: Photo taken from the southeast end of the location, facing northwest. Photo shows overview of the location. Recent reclamation work evident.



Photo 4: Photo taken from the location. Inspector found evidence of desirable perennial vegetation throughout location. Inspector also found germination of undesirable weedy plant species such as kochia. Continue performing weed management.

Inspection Photos
Operator: WIEPKING-FULLERTON ENERGY LLC - 96340
Location ID: 321883



Photo 5: Photo taken from the access road, east of the location, facing west. Photo shows section of the access road NOT included in the variance request appears to have had reclamation work conducted.



Photo 6: Photo taken from the access road, east of the location, facing west. Photo shows the north/south section of the access road that is included in the variance request.



Photo 7: Photo taken from the southern end, of the north/south traveling section of the access road included in the variance request. Photo shows section of access road where degradation is evident. The north/south traveling section of the access road is on a slope and stormwater and vehicular appears to have deepened vehicle ruts in areas as. Stormwater also appears to have “cut”, or washed out, areas of the access road creating gully formations. 6 foot measuring stick for reference.



Photo 8: Continued from photo 7.



Photo 9: 2015 aerial imagery. Photo shows the access road outlined in the variance request. The section of access road in red outlines areas where degradation is evident.