

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
05/15/2018

Submitted Date:  
05/17/2018

Document Number:  
682503357

**FIELD INSPECTION FORM**

Loc ID 321883 Inspector Name: Trujillo, Aaron On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96340  
Name of Operator: WIEPKING-FULLERTON ENERGY LLC  
Address: 96 GLENMOOR LN  
City: ENGLEWOOD State: CO Zip: 80113

**Findings:**

3 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Arthur, Denise		denise.arthur@state.co.us	
		ldboonepar@aol.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208333	WELL	PA	07/20/2010	SI	017-07268	RHOADES 1	RI

**General Comment:**

This is a final reclamation and stormwater inspection in response to a 1001.c, 502.b reclamation variance request. Operator submitted doc. #401521874 on 03/29/2018 requesting that ~1.25 miles of access road be left un-reclaimed per the request of the surface owner. This inspection is to identify the current conditions of the location and/or any concerns that may exist, and is part of the detailed technical review process per the "1001.c: Reclamation Variances and Waivers" operator guidance document. Please refer to the guidance document for additional details.

Please note that the submission of a variance request does not guarantee approval. The COGCC will provide notice to WFE once an official decision has been made.

All portions of the location not included in the variance request remain under COGCC jurisdiction until passing final reclamation; any corrective action(s) from previous inspections that have not been addressed will remain applicable.

**Inspected Facilities**

Facility ID: 208333 Type: WELL API Number: 017-07268 Status: PA Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control **Fail** \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment:

Reclamation appears to have been conducted on the location per doc. #401294492 and CAs from inspection #673504009. Germination evident, reclamation in-process.

Inspector found evidence that surface owner appears to utilize the road to access areas of his or her the property. However, degradation (due to stormwater, use, or both) evident along the North/south section of the access road. Access road does not appear to be stabilized; maintenance and stormwater management does not appear to be occurring. See attached photos.

Corrective Action:

Date

Overall Final Reclamation

Well Release on Active Location

Multi-Well Location

**COGCC Comments**

Comment	User	Date
Form 6s #1897495 shows plugging date of 7/20/2010	trujilloam	05/16/2018
Inspection doc. #663901223 dated 6/11/2012 failed reclamation of the location and access road and required operator to "RIP AND CONTOUR LEASE ROAD AND LOCATION, SEED AND CONTROL WEEDS" by 9/11/2012.		
Inspection doc. #673504009 dated 1/12/2017 failed reclamation of the location and access road and required operator to "Recontour the access road. Decompact soils by cross ripping to a minimum depth of 18 inches. Reseed the location and access road to facilitate vegetation establishment. Stabilize the disturbed soils until vegetation establishes (e.g. weed free mulch)" by 4/28/2017.		
Operator appears to have submitted doc. #401294492 on 5/26/2017 in response to corrective actions from inspection #673504009. Operator indicates that a variance will be submitted for the road. Variance request was submitted ~ten (10) months later.		
It is noted that the 502.b variance request has been submitted almost eight (8) years after the plugging and abandonment date, and in response to two (2) corrective action inspections in the last six (6) years.		

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682503358	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4465912">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4465912</a>