

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/17/2018

Submitted Date:

05/17/2018

Document Number:

690001588**FIELD INSPECTION FORM**

Loc ID 333137 Inspector Name: Carlile, Craig On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10633
 Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
 Address: 1801 CALIFORNIA STREET #2500
 City: DENVER State: CO Zip: 80202

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		cogcc.inspections@crestonepr.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241539	WELL	PR	02/22/1995	GW	123-09328	ARISTOCRAT ANGUS 14-3	PR
271404	WELL	PR	06/12/2014	GW	123-22045	ARISTOCRAT ANGUS 14-3A	PR
425276	WELL	PR	03/25/2015	GW	123-34332	ARISTOCRAT ANGUS 3-3	PR
425327	WELL	PR	12/13/2013	GW	123-34347	ARISTOCRAT ANGUS 0-8-3	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

Type			corrective date
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		

Comment:	
Corrective Action:	Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		
Comment:					
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)	230 Bbl				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shared with crude oil tank.				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.248860,-104.656820
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO			
Comment:				
Corrective Action:				Date:

Flaring:

Type	Ignitor/Combustor			
Comment:				
Corrective Action:				Date:

Inspected Facilities			
Facility ID: <u>241539</u>	Type: <u>WELL</u>	API Number: <u>123-09328</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>PR</u>	Corrective Action: <input style="width: 100%;" type="text"/>		Date: <input style="width: 100%;" type="text"/>
BradenHead			
Comment: <u>Bradenhead plumbed to surface.</u>	Corrective Action: <input style="width: 100%;" type="text"/>		Date: <input style="width: 100%;" type="text"/>
Facility ID: <u>271404</u>	Type: <u>WELL</u>	API Number: <u>123-22045</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>PR</u>	Corrective Action: <input style="width: 100%;" type="text"/>		Date: <input style="width: 100%;" type="text"/>
BradenHead			
Comment: <u>Bradenhead plumbed to surface.</u>	Corrective Action: <input style="width: 100%;" type="text"/>		Date: <input style="width: 100%;" type="text"/>
Facility ID: <u>425276</u>	Type: <u>WELL</u>	API Number: <u>123-34332</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>PR</u>	Corrective Action: <input style="width: 100%;" type="text"/>		Date: <input style="width: 100%;" type="text"/>
BradenHead			
Comment: <u>Bradenhead plumbed to surface.</u>	Corrective Action: <input style="width: 100%;" type="text"/>		Date: <input style="width: 100%;" type="text"/>
Facility ID: <u>425327</u>	Type: <u>WELL</u>	API Number: <u>123-34347</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>PR</u>	Corrective Action: <input style="width: 100%;" type="text"/>		Date: <input style="width: 100%;" type="text"/>
BradenHead			
Comment: <u>Bradenhead plumbed to surface.</u>	Corrective Action: <input style="width: 100%;" type="text"/>		Date: <input style="width: 100%;" type="text"/>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine inspection.	carlilec	05/17/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690001589	Wells	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4466334
690001590	Battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4466335