



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the western portion of the project area from the northwestern corner facing southward. Revegetation is progressing on fill slope with rubber rabbitbrush (*Chrysothamnus nauseosus*) and western wheatgrass (*Pascopyrum smithii*).



Photo 3. View of the southern portion of the project area from the southeastern corner of the working area facing westward.



Photo 4. View of musk thistles (*Carduus nutans*) in the southern project area.



Photo 5. View of unused equipment within the western interim reclamation area.



Photo 6. View of erosional channel forming within the southern portion of the project area.