

Location			
Lease Road:			
Type	Main		
comment:	Main road to Stromberger 13-32 (API #05-123-26334) battery is adequate		
Corrective ActionL		Date:	
Type	Access		
comment:	Acess road to Stromberger 13-32 (API #05-123-26334) is non-existent. Also gate is locked at county road with a lock that will not open with the key provided to COGCC by Noble. Had to climb over gate and walk about 1/4 mile to well through newly planted corn. Location is not accessible during normal business hours.		
Corrective ActionL	Provide key, combinations, or altenate method of access. Repair and maintain lease road. Comply with Rule 204.	Date:	06/18/2018

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Statewide unused equipment, weeds, waste, and trash requirements. Found various unused equipment and debris at wellsite.		
Corrective Action:	Comply with Rule 603.f .	Date:	06/18/2018

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	WELLHEAD		
Comment:	Stromberger 13-32 (API #05-123-26334) has iron panel fence.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment: 48" ECD controls oil tank VOCs			
Corrective Action:			Date:
Type: Plunger Lift	# 2		

Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Shares berms w/ produced oil tanks & produced H2O vault.			
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	35 Bbls.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Shares berms w/ produced oil tanks & produced H2O tank.			
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		40.479920,-104.842453
Comment:					

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Shares berms w/ produced H2O tank & vault.				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 292414 Type: WELL API Number: 123-26334 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: SI. Appears to be TA as all other equipment downstream from well master valve has been disconnected.

Corrective Action: _____ Date: _____

BradenHead

Comment: Bradenhead appears plumbed to surface.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<u>Several other wells that had previously been associated with this facility appear to have been P&A'd. Stromberger 1-13, 13-31, & 13-35.</u>	evinsb	05/18/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691200116	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4468110