

Inspection Photo
ALP 24-16B1 (J24NW)
API# 045-08105
Inspection # 689301146



Location Photo #1,

Location Photo # 2

Inspection Photo
ALP 24-16B1 (J24NW)
API# 045-08105
Inspection # 689301146



Location Photo # 3, Staining in Tank Battery containment



Location Photo # 4, Staining in Tank Battery containment

Inspection Photo
ALP 24-16B1 (J24NW)
API# 045-08105
Inspection # 689301146



Location Photo #5, Condensate spilled in containment



Location Photo # 6, Staining in Tank Battery containment

**Inspection Photo
ALP 24-16B1 (J24NW)
API# 045-08105
Inspection # 689301146**



Location Photo #7, Staining in Tank Battery containment



Location Photo #8, Leaking liquid line from back of separator

Inspection Photo
ALP 24-16B1 (J24NW)
API# 045-08105
Inspection # 689301146



Location Photo #9, Leaking liquid line from back of separator



Location Photo # 10, Slope erosion on south slope

Inspection Photo
ALP 24-16B1 (J24NW)
API# 045-08105
Inspection # 689301146



Location Photo #11, Slope erosion on south slope

Location Photo # 12, Slope erosion on south slope

Inspection Photo
ALP 24-16B1 (J24NW)
API# 045-08105
Inspection # 689301146



Location Photo #13, Slope erosion on south slope

Location Photo # 14, Slope erosion on south slope

Inspection Photo
ALP 24-16B1 (J24NW)
API# 045-08105
Inspection # 689301146



Location Photo #15, Slope erosion on south slope



Location Photo # 16, Slope erosion on south slope

Inspection Photo
ALP 24-16B1 (J24NW)
API# 045-08105
Inspection # 689301146



Location Photo #17, Riling occurring on North side of location

Location Photo # 18

Inspection Photo
ALP 24-16B1 (J24NW)
API# 045-08105
Inspection # 689301146



Location Photo #19, continued riling on North side of location

Location Photo # 20

Inspection Photo
ALP 24-16B1 (J24NW)
API# 045-08105
Inspection # 689301146



**Location Photo #21, slope erosion next to
meter run**

