

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/16/2018

Submitted Date:

05/21/2018

Document Number:

690100533

**FIELD INSPECTION FORM**

Loc ID 322685 Inspector Name: Maclaren, Joe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**OGCC Operator Number: 10311Name of Operator: SRC ENERGY INCAddress: 1675 BROADWAY SUITE 2600City: DENVER State: CO Zip: 80202**Findings:**3 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@srcenergy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244080	WELL	PR	09/01/2017	OW	123-11873	FRAKER 1	EG

**General Comment:**

COGCC engineering integrity inspection (flowline) performed as a followup to 2017 flowline NTO inspection (1000' buffer) Doc #680704244 conducted on 06/28/2017 that outlines: NOT IN USE: 1-2" steel and 1-1" steel process risers marked and tagged out for removal.

Details of this inspection are outlined in the flowline section of this report. Photos uploaded.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Action Required Completed; Signage added at battery.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:			
		Date:	_____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Flow Line	#		
Comment:	No unused risers were observed on this well pad/ location.		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 244080 Type: WELL API Number: 123-11873 Status: PR Insp. Status: EG**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100540	Signage at wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4468854">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4468854</a>
690100541	Horizontal separator (flowlines at inlet)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4468855">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4468855</a>