



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of area that was recently graded to direct stormwater flows in the southeastern portion of the project area.



Photo 3. View of cobble run-down in the southern portion of the project area.



Photo 4. View of another cobble run-down in the southern project area.