



**Photo 1. View of cobble armoring and diversion in the southern portion of the project area.**



**Photo 2. View of recently graded diversion in the southeastern project area.**



**Photo 3. View of cobble run-downs in the western portion of the project area.**



**Photo 4. View of rock checks along the access road.**