



**Photo 1. View of check dams in the southern portion of the project area. Appear to be functioning.**





**Photo 2. View of another check dam in the southern project area.**





**Photo 3. View of recently graded diversion and berm. Seedlings observed on berm.**





**Photo 4. View of Scotch thistles (*Onopordum acanthium*) in the western portion of the project area.**