

Inspection Photos
Location Name: MOC 32C CE&P Facility
433736




Facility 443736



Open gate

Inspection Photos
Location Name: MOC 32C CE&P Facility
433736



Unsecured gate



Open gate

Inspection Photos
Location Name: MOC 32C CE&P Facility
433736



Unsecured gate



Debris (buckets), hoses on liner

Inspection Photos
Location Name: MOC 32C CE&P Facility
433736



Holes in netting



Holes in netting

Inspection Photos
Location Name: MOC 32C CE&P Facility
433736



Debris



Debris