

Inspection Photos
Location Name: F.S. Duncan B 5
API: 05-081-06864



Photo 1. Overview of location taken at entrance facing southwest.

Inspection Photos
Location Name: F.S. Duncan B 5
API: 05-081-06864



Photo 2. Erosion gully transporting sediment off location. (1 of 2)



Photo 3. Erosion gully transporting sediment off location. (2 of 2)