

Inspection Photos
Location Name: Duncan Van Schaick
612N100W 29SWNW
Location ID: 333337



Photo 1. Overview of location taken at entrance facing south.