

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/08/2018

Submitted Date:

05/22/2018

Document Number:

689801128

**FIELD INSPECTION FORM**

Loc ID 313150 Inspector Name: Waldron, Emily On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

| Contact Name  | Phone          | Email                | Comment                         |
|---------------|----------------|----------------------|---------------------------------|
| Fillpot, Greg | (307) 299-3829 | gfillpot@hilcorp.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 262836      | WELL | PR     | 11/01/2017  | OW         | 081-07084 | VAN SCHAICK C 10 | SI          |

**General Comment:**

[Routine FIU inspection.](#)

**Location**

Overall Good:

**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | WELLHEAD             |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | BATTERY              |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

| Type                            | #   |       | corrective date |
|---------------------------------|-----|-------|-----------------|
| Type: Pump Jack                 | # 1 |       |                 |
| Comment:                        |     |       |                 |
| Corrective Action:              |     | Date: |                 |
| Type: Deadman # & Marked        | # 4 |       |                 |
| Comment:                        |     |       |                 |
| Corrective Action:              |     | Date: |                 |
| Type: Horizontal Heater Treater | # 1 |       |                 |
| Comment: 40.97181, -108.66656   |     |       |                 |
| Corrective Action:              |     | Date: |                 |
| Type: Bird Protectors           | #   |       |                 |
| Comment:                        |     |       |                 |
| Corrective Action:              |     | Date: |                 |
| Type: Gas Meter Run             | # 1 |       |                 |
| Comment: 40.97195, -108.66659   |     |       |                 |
| Corrective Action:              |     | Date: |                 |

**Tanks and Berms:**

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------|---|----------|------|---------|--------|
|          |   |          |      |         |        |

|                    |          |                     |                     |             |                       |       |  |
|--------------------|----------|---------------------|---------------------|-------------|-----------------------|-------|--|
| CRUDE OIL          | 2        | 400 BBLs            | HEATED STEEL AST    |             | 40.971830,-108.666730 |       |  |
| Comment:           |          |                     |                     |             |                       |       |  |
| Corrective Action: |          |                     |                     |             |                       | Date: |  |
| <b>Paint</b>       |          |                     |                     |             |                       |       |  |
| Condition          | Adequate |                     |                     |             |                       |       |  |
| Other (Content)    |          |                     |                     |             |                       |       |  |
| Other (Capacity)   |          |                     |                     |             |                       |       |  |
| Other (Type)       |          |                     |                     |             |                       |       |  |
| <b>Berms</b>       |          |                     |                     |             |                       |       |  |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |                       |       |  |
| Metal              | Adequate |                     |                     | Adequate    |                       |       |  |
| Comment:           |          |                     |                     |             |                       |       |  |
| Corrective Action: |          |                     |                     |             |                       | Date: |  |
| <b>Venting:</b>    |          |                     |                     |             |                       |       |  |
| Yes/No             | NO       |                     |                     |             |                       |       |  |
| Comment:           |          |                     |                     |             |                       |       |  |
| Corrective Action: |          |                     |                     |             |                       | Date: |  |
| <b>Flaring:</b>    |          |                     |                     |             |                       |       |  |
| Type               |          |                     |                     |             |                       |       |  |
| Comment:           |          |                     |                     |             |                       |       |  |
| Corrective Action: |          |                     |                     |             |                       | Date: |  |

**Inspected Facilities**

Facility ID: 262836 Type: WELL API Number: 081-07084 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description      | URL   |
|--------------|------------------|---|
| 689801129    | Inspection Photo | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4471091">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4471091</a> |