

HALLIBURTON

iCem[®] Service

PDC ENERGY-EBUS

Date: Wednesday, September 20, 2017

Josephine 190-204 Production

Job Date: Monday, September 04, 2017

Sincerely,

Bryce Hinsch

Legal Notice

Disclaimer:

All information in this report is provided subject to the terms and conditions which govern the services provided by Halliburton. Halliburton personnel use their best efforts in gathering information and their best judgment in interpreting it, but any interpretation, research, analysis or recommendation furnished by Halliburton are opinions based upon inferences from measurements and empirical relationships and assumptions, which inferences and empirical relationships and assumptions are not infallible, and with respect to which professionals in the industry may differ. Accordingly, HALLIBURTON IS UNABLE TO GUARANTEE THE ACCURACY OF ANY CHART INTERPRETATION, RESEARCH ANALYSIS, OR JOB RECOMMENDATION and any interpretation or recommendation is not for use of or reliance upon by any third party. The customer has full responsibility for any of its decisions which are based on the information provided in this report.

Table of Contents

1.0 Cementing Job Summary 4

 1.1 Executive Summary4

2.0 Real-Time Job Summary 9

 2.1 Job Event Log9

3.0 Attachments..... 12

 3.1 PDC Josephine 190-204 Production Job Chart.....12

1.0 Cementing Job Summary

1.1 Executive Summary

Halliburton appreciates the opportunity to perform the cementing services on the **Josephine 190-204** cement **production** casing job. A pre-job safety meeting was held before the job where details of the job were discussed, potential safety hazards were reviewed, and environmental compliance procedures were outlined.

Approximately 20 bbls of cement were returned to surface.

Halliburton maintains a continuous quality improvement process and appreciates any comments or suggestions that you may have. Halliburton again thanks you for the opportunity to perform service work on this well. We hope to be your solutions provider for future projects.

Respectfully,

Halliburton [Fort Lupton]

HALLIBURTON

Cementing Job Summary

The Road to Excellence Starts with Safety

Sold To #: 304535		Ship To #: 3797102		Quote #:		Sales Order #: 0904270849				
Customer: PDC ENERGY-EBUS				Customer Rep:						
Well Name: JOSEPHINE		Well #: 190-204		API/UWI #: 05-123-44681-00						
Field: WATTENBERG	City (SAP): KERSEY	County/Parish: WELD		State: COLORADO						
Legal Description: SW NE-19-5N-64W-1849FNL-2214FEL										
Contractor: ENSIGN DRLG		Rig/Platform Name/Num: ENSIGN 158								
Job BOM: 7523 7523										
Well Type: HORIZONTAL OIL										
Sales Person: HALAMERICA\H139013				Srv Supervisor:						
Job										
Formation Name										
Formation Depth (MD)		Top			Bottom					
Form Type				BHST						
Job depth MD		12902ft		Job Depth TVD						
Water Depth				Wk Ht Above Floor		4				
Perforation Depth (MD)		From			To					
Well Data										
Description	New / Used	Size in	ID in	Weight lbm/ft	Thread	Grade	Top MD ft	Bottom MD ft	Top TVD ft	Bottom TVD ft
Casing		9.625	8.921	36			0	1649		0
Casing		5.5	4.778	20			0	12902		0
Open Hole Section			8.5				1675	12904		0
Tools and Accessories										
Type	Size in	Qty	Make	Depth ft		Type	Size in	Qty	Make	
Guide Shoe	5.5		KLX	12902		Top Plug	5.5		HES	
Float Shoe	5.5					Bottom Plug	5.5	1	KLX	
Float Collar	5.5					SSR plug set	5.5		HES	
Insert Float	5.5					Plug Container	5.5	1	HES	
Stage Tool	5.5					Centralizers	5.5		HES	
Fluid Data										
Stage/Plug #: 1										
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal	
1	Mud Flush III (Powder)	Mud Flush III	50	bbl	8.4					
42 gal/bbl		FRESH WATER								
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal	

iCem® Service

(v. 4.4.18)

HALLIBURTON

Cementing Job Summary

2	12.0 lb/gal Tuned Spacer III	Tuned Spacer III	50	bbl	12	3.16			
35.20 gal/bbl		FRESH WATER							
176.58 lbm/bbl		BARITE, BULK (100003681)							
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/mi n	Total Mix Fluid Gal
3	ElastiCem Cap	ELASTICEM (TM) SYSTEM	150	sack	13.2	1.57		5	7.52
7.52 Gal		FRESH WATER							
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/mi n	Total Mix Fluid Gal
4	13.2# ElastiCem	ELASTICEM (TM) SYSTEM	1922	sack	13.2	1.57		6	7.53
7.53 Gal		FRESH WATER							
61.10 lbm		TYPE I / II CEMENT, BULK (101439798)							
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/mi n	Total Mix Fluid Gal
5	Displacement fluid		286	bbl	8.33				
Cement Left In Pipe		Amount	33 ft		Reason			Shoe Joint	

2.0 Real-Time Job Summary

2.1 Job Event Log

Type	Seq. No.	Activity	Graph Label	Date	Time	Source	Comb Pump Rate (bbl/min)	DS Pump Press (psi)	DH Density (ppg)	Comments
Event	1	Call Out	Call Out	9/4/2017	05:30:00	USER				called out to be on location at 1000.
Event	2	Arrive At Loc	Arrive At Loc	9/4/2017	11:24:00	USER				cementer late to location due to paperwork issue on pickup that was sorted out by the shop. All crew arrived on location. Rig still running casing.
Event	3	Assessment Of Location Safety Meeting	Assessment Of Location	9/4/2017	11:27:00	USER				Met with company rep to go over job. TD 12904, 8.5 OH 20%xs. 5.5 20# casing 12905.19, PC 9.625 36# set at 1649. KLX plug hand on lcoation for wet shoe system.
Event	4	Safety Meeting - Pre Rig-Up	Safety Meeting - Pre Rig-Up	9/4/2017	11:29:00	USER				Discuss rig up plan, taking breaks and staying hydrated.
Event	5	Rig-Up Equipment	Rig-Up Equipment	9/4/2017	11:38:00	USER				
Event	6	Rig-Up Completed	Rig-Up Completed	9/4/2017	13:30:00	USER				rig still running in casing.
Event	7	Other	Other	9/4/2017	14:51:54	USER	0.00	-160.00	8.30	Rig on bottom, rigging down casing crew.
Event	8	Safety Meeting - Pre Job	Safety Meeting - Pre Job	9/4/2017	16:00:00	USER	0.00	-162.00	8.30	ALL HES, Rig and Company Personnel. Discuss job procedure, SWA, and any contingency plans. Rig will be running through choke during cementing. and bypass during circulation.

Event	9	Test Lines	Test Lines	9/4/2017	16:58:13	COM4	0.00	4913.00	8.47	Test kickouts 500 PSI total test 5000 PSI.
Event	10	Pump Spacer 1	Pump Spacer 1	9/4/2017	17:01:08	COM4	2.40	168.00	8.28	50 BBLS MudFlush 4 BPM 660 PSI.
Event	11	Pump Spacer 2	Pump Spacer 2	9/4/2017	17:12:50	COM4	2.50	585.00	8.85	50 BBLS Tuned SPacer 12 PPG 4 BPM, 683 PSI.
Event	12	Pump Cap Cement	Pump Cap Cement	9/4/2017	17:21:20	COM4	5.10	647.00	12.09	150 SKS 13.2 PPG, 42 BBL 7 BPM 1000 PSI.
Event	13	Pump Cement	Pump Cement	9/4/2017	17:29:13	COM4	4.20	338.00	12.92	1922 SKS 13.2 PPG, 537 BBLS, 7 BPM, 454 PSI.
Event	14	Shutdown	Shutdown	9/4/2017	18:59:19	COM4	0.00	-10.00	13.69	
Event	15	Clean Lines	Clean Lines	9/4/2017	18:59:22	COM4	0.00	-14.00	13.70	Wash up to pit.
Event	16	Drop Plug	Drop Plug	9/4/2017	19:11:17	COM4	0.00	-40.00	8.27	THird party double top plug.
Event	17	Pump Displacement	Pump Displacement	9/4/2017	19:11:19	COM4	0.00	-40.00	8.27	286 BBLS Calculated displacement, 4 BPM until we catch cement then raise it to 8 BPM.
Event	18	Bump Plug	Bump Plug	9/4/2017	19:56:23	COM4	0.00	2622.00	8.36	Reached Calculated displacement and got a bump, from 2300 PSI to 2520 PSI. Pressure fell slowly while we watched it after that.. Pumped into it to pump the 5 BBLS wet shoe.
Event	19	Other	Other	9/4/2017	20:03:41	USER	4.00	3451.00	8.39	Pressure increased to 4000 PSI and fell off good this time. Customer rep and tool hand confident tool was opened good at this time, and pumped 5 BBLS after this and shut down.
Event	20	Check Floats	Check Floats	9/4/2017	20:06:20	USER	0.00	393.00	8.31	got 2 BBLS back. Held.
Event	21	Pre-Rig Down Safety	Pre-Rig Down Safety	9/4/2017	20:10:00	USER	0.00	-38.00	8.27	Discuss sending stuff out

		Meeting	Meeting							the v-door, team lift, and trapped pressure.
Event	22	Rig-Down Equipment	Rig-Down Equipment	9/4/2017	20:15:00	USER	8.80	59.00	8.29	
Event	23	Rig-Down Completed	Rig-Down Completed	9/4/2017	22:00:00	USER				
Event	24	Safety Meeting - Departing Location	Safety Meeting - Departing Location	9/4/2017	22:30:00	USER				Discuss jounry management, Route home and DOT HOS.