

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401633573
Date Received:
05/08/2018

FIR RESOLUTION FORM

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 1801 CALIFORNIA STREET #2500
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
.		cogcc.inspections@crestonepr.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682403506
Inspection Date: 04/25/2018 FIR Submit Date: 04/30/2018 FIR Status: _____

Inspected Operator Information:

Company Name: CRESTONE PEAK RESOURCES OPERATING LLC Company Number: 10633
Address: 1801 CALIFORNIA STREET #2500
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 428577

Location Name: Ruegge Facility Number: 4H-N165 County: _____
Qtrqtr: SWS Sec: 4 Twp: 1N Range: 65W Meridian: 6
Latitude: 40.074992 Longitude: -104.677897

FACILITY - API Number: 05-123- -00 Facility ID: 428577

Facility Name: Ruegge Facility Number: 4H-N165
Qtrqtr: SWS Sec: 4 Twp: 1N Range: 65W Meridian: 6
Latitude: 40.074992 Longitude: -104.677897

CORRECTIVE ACTIONS:

1 ☒ CA# 116140

Corrective Action: Comply with Rule 1002. Corrective action date is being back-dated to when the Operator should have been in compliance with this rule. Date: 03/25/2018

Response: CA COMPLETED Date of Completion: 05/07/2018

Operator Comment: Follow up, the inspector requested an estimate of the volume of topsoil. The stock piled topsoil is estimated at 6200 cubic yards.
Topsoil at the location was salvaged and has been stockpiled. Topsoil in areas where the former Stelling facility was did not exist and all fill material was removed or recontoured during the initial construction operations.

Topsoil along flowline areas had been salvaged utilizing a double ditching method, and segregated during excavation, then backfilled immediately. Vegetation was grubbed along the flowline corridor as appropriate.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this Field Inspection Report Resolution (FIRR) form acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. This location is currently under enforcement action; therefore, this FIRR response by Staff is being entered for notification and documentation only and is not intended to provide the Operator the opportunity to resolve the alleged violations without the imposition of a penalty, pursuant to Rule 522.c.(1).

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: John Gardner

Signed: _____

Title: Sr. Env. Specialist

Date: 5/8/2018 1:22:24 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

401633573	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files