

Final Reclamation and Stormwater Inspection

May 22, 2018

Operator: KERR MCGEE OIL & GAS # 47120

Location ID: 317593

Inspection Document #: 674902121

Weld County, CO

SWSW Section 1 T1N R67W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: KERR MCGEE /1N67W1
Location ID: 317593



Photo 1. Photo taken from the well location looking towards the facility, facing East. Appears the Operator has not performed any reclamation activities on the well location itself but has on the facility.



Photo 2. Photo taken from the well location, facing North. A List B Colorado Noxious weed species, musk thistle (*Carduus nutans*), is found at low densities throughout the site .

Inspection Photos
Location Name: KERR MCGEE /1N67W1
Location ID: 317593



Photo 3. Photo taken from the facility, facing South. Appears the Operator has performed final reclamation activities, with the evidence of drilling rows and straw crimped mulch. However, the majority of the site is covered in weedy, annual vegetation which includes but not limited to field bindweed and kochia, with little perennial grass cover establishment. A List B Colorado Noxious weed species, musk thistle (*Carduus nutans*), is found at low densities throughout the site .



Photo 4. Photo taken within facility area. Note the musk thistle and kochia. See comments from Photo 3.

Inspection Photos
Location Name: KERR MCGEE /1N67W21
Location ID: 317593



Photo 5. Photo taken from the South end of the facility. The bucket hole needs to be re-contoured and re-seeded.



Photo 6. Photo taken from the Southeast end of the facility. Debris removal needed.

Inspection Photos
Location Name: KERR MCGEE /1N67W2
Location ID: 317593



Photo 7. Photo taken from the South end of the access road between the well and the facility, facing West. Appears stormwater runoff is causing rill erosion along the remaining access road between the well and the facility.



Photo 8. Photo taken from the South end of the access road between the well and the facility, facing West. See comment from Photo 7.