

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/23/2018

Submitted Date:

05/25/2018

Document Number:

688800106

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
313600 _____ Hughes, Jim _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46685
Name of Operator: KINDER MORGAN CO2 CO LP
Address: 1001 LOUISIANA ST SUITE 1000
City: HOUSTON State: TX Zip: 77002

Findings:

- 7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
KinderMorgan		CO2Source_Regulatory@kindermorgan.com	SW Inspection Reports
Roy, Catherine		catherine.roy@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278718	PIT	AC			-	YA #5 (YWD)	EI
278759	WELL	PR	11/10/2005	STRT	083-06623	YA 5	EI
313600	LOCATION	AC			-	YA-N37N18W 13NENE	EI

General Comment:

On May 23, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Kinder Morgan YA-5 location as it relates to Remediation Project #9857. Area 145 Reclamation Specialist Catherine Roy and Kinder Morgan Representative Mike Hannigan were on site during this site visit. For the most recent field inspection report of this facility, please refer to document #680601107. Please refer to document #200440394 for more information regarding remediation efforts on this location. This inspection was conducted to determine the current surface condition of the area where the drilling pits existed.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Location sign near entrance.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Stock panel enclosure around well head.		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 278718 Type: PIT API Number: - Status: AC Insp. Status: EI

Facility ID: 278759 Type: WELL API Number: 083-06623 Status: PR Insp. Status: EI

Facility ID: 313600 Type: LOCATION API Number: - Status: AC Insp. Status: EI

Environmental

Spill/Remediation:

Comment: [Please refer to REM Project #9857 for more information.](#)

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Drilling Pit Lined: Pit ID: 278718 Lat: 37.469257 Long: -108.776128

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: c

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date: _____

COGCC Comments

Comment	User	Date
On May 23, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Kinder Morgan YA-5 location as it relates to Remediation Project #9857. Area 145 Reclamation Specialist Catherine Roy and Kinder Morgan Representative Mike Hannigan were on site during this site visit. For the most recent field inspection report of this facility, please refer to document #680601107. Please refer to document #200440394 for more information regarding remediation efforts on this location. This inspection was conducted to determine the current surface condition of the area where the drilling pits existed.	hughesj	05/25/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800107	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4475488