

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/22/2018

Submitted Date:

05/24/2018

Document Number:

688301864**FIELD INSPECTION FORM**Loc ID 378078 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 15850Name of Operator: CHANDLER & ASSOCIATES LLCAddress: 475 17TH ST STE 1000City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Anderson, Eric	(303) 798-0356	eric.anderson@highlandsnr.com	Principal Agent/Land Manager
Miller, Stephen	(361) 230-9375	stephen.miller@highlandsnr.com	Designated Agent/Engineer

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204517	WELL	DA	03/05/1973	DA	005-06602	SMOKEY HILL-STATE 4-22	DA

General Comment:

PA. Cement to surface on 5/24/2018. Cut, cap and cover still to be completed with all other COAs on Form 6N.

Inspected FacilitiesFacility ID: 204517 Type: WELL API Number: 005-06602 Status: DA Insp. Status: DA**Cement**Cement ContractorContractor Name: Halliburton/Vitali

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): 283

Good Return During Job: _____

Cement Type: Class GComment:5/22/2018Set 50 sxs Class G cement from 1463-1293.Set 83 sxs Class G, 2% CaCl cement from 961 to 637 (tagged).Set 150 sxs Class G, 13.5 cement from 250-0 with no returns to surface. Tagged at 188'5/24/2018Pumped 63 sxs to surface (13 ppg, 3 bpm).

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688301895	Highlands Smokey Hill- State 4-22 PA	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4475843