

Inspection Photos

Location Name: Sandy Hill Land Application Site, Facility: 448950

Inspection Date: 05/24/2018



Photo 1 – Northwest corner of land application area, looking at gate onto State Landboard property.



Photo 2 – From northwest corner of land application area, looking south along berm and ditch at western fenceline.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Sandy Hill Land Application Site, Facility: 448950

Inspection Date: 05/24/2018



Photo 3 – Failure of berm, runoff contained in ditch on western boundary of land application area



Photo 4 - Failure of berm, runoff contained in ditch on western boundary of land application area



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Sandy Hill Land Application Site, Facility: 448950

Inspection Date: 05/24/2018



Photo 5 – Looking west onto State Landboard property at area of spill ID 452946



Photo 6 - Looking west onto State Landboard property at area of spill ID 452946



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Sandy Hill Land Application Site, Facility: 448950

Inspection Date: 05/24/2018



Photo 7 – From center-west edge of land application area looking north along berm and ditch on western property line.



Photo 8 – From center-west edge of land application area looking south along berm and ditch on western property line.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Sandy Hill Land Application Site, Facility: 448950

Inspection Date: 05/24/2018



Photo 9 – From southwest corner of land application area looking east along southern property line. Winick property (Spill 454016) is to the right of fence.



Photo 10 - From southwest corner of land application area looking southeast across southern property line. Viewing Winick property (Spill 454016) on far side of the fence.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Sandy Hill Land Application Site, Facility: 448950

Inspection Date: 05/24/2018



Photo 11 – From southwest corner of land application area looking northeast.



Photo 12 - From southwest corner of land application area looking north along western property line.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Sandy Hill Land Application Site, Facility: 448950

Inspection Date: 05/24/2018



Photo 13 – From northwest corner of land application area, looking south.



Photo 14 – From northwest corner of land application area, looking southeast.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Sandy Hill Land Application Site, Facility: 448950

Inspection Date: 05/24/2018



Photo 15 – From northwest corner of land application area, looking east.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources