

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/29/2018

Submitted Date:

05/29/2018

Document Number:

689301200**FIELD INSPECTION FORM**Loc ID 335442 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Ghan, Scott	970-744-8128	sgghan@vnrenergy.com	SR. EH&S
Aaron, Axelson	230-0926	aaxelson@vnrenergy.com	Sr. Production Foreman

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282722	WELL	PR	10/14/2009	GW	045-11801	BBC 42C-23-692	PR
282723	WELL	PR	10/13/2009	GW	045-11800	BBC 42A-23-692	PR
282724	WELL	PR	09/24/2009	GW	045-11799	BBC 12B-24-692	PR
282726	WELL	PR	09/22/2009	GW	045-11798	BBC 13D-24-692	PR
282728	WELL	PR	09/22/2009	GW	045-11797	BBC 12D-24-692	PR
299502	WELL	PR	09/24/2009	GW	045-17688	BBC 12C-24-692	PR
299503	WELL	PR	04/17/2012	GW	045-17689	BBC 42B-23-692	PR
299504	WELL	PR	09/30/2009	GW	045-17690	BBC 12A-24-692	PR
299505	WELL	PR	10/02/2009	GW	045-17691	BBC 42D-23-692	PR

General Comment:[Routine Field Inspection](#)

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☒**Emergency Contact Number:**

Comment:	1-800-921-8252	
Corrective Action:		Date:

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	
Type	TRASH		
Comment:			
Corrective Action:		Date:	
Type	WEEDS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Hog Panel Fencing		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Livestock panels		
Corrective Action:		Date:	

Equipment:

Type: Horizontal Heated Separator	# 9		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 9		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 4		
Comment:	Chemical units at Wellheads		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	500 BBLs	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	4	500 BBLs	STEEL AST		,	
Comment:	Centralized Battery					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	YES		
Comment:	Bradenheads open		
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	282722	Type:	WELL	API Number:	045-11801	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	282723	Type:	WELL	API Number:	045-11800	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	282724	Type:	WELL	API Number:	045-11799	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	282726	Type:	WELL	API Number:	045-11798	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	282728	Type:	WELL	API Number:	045-11797	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	299502	Type:	WELL	API Number:	045-17688	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	299503	Type:	WELL	API Number:	045-17689	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	299504	Type:	WELL	API Number:	045-17690	Status:	PR	Insp. Status:	PR

Producing Well			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	

Facility ID:	299505	Type:	WELL	API Number:	045-17691	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	

--	--	--	--

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Berms						
				Material Handling And Spill Prevention		
Seeding						
		Gravel				
Slope Roughening						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689301201	Inspection Photo 689301201	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4476711