

Location

| | | | |
|--------------------|--|-------|--|
| Lease Road: | | | |
| Type | Main | | |
| comment: | Main road to Kinzer 23-3C (API# 05-123-19423), Kinzer 23-3B (API# 05-123-19415), Kinzer 23-3D (API# 05-123-19424) is adequate. | | |
| Corrective ActionL | | Date: | |
| Type | Access | | |
| comment: | Access road to Kinzer 23-3B (API# 05-123-19415) is adequate. | | |
| Corrective ActionL | | Date: | |

Overall Good:

Emergency Contact Number:

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|--------------------|--|-------|--|
| Fencing/: | | | |
| Type | | | |
| Comment: | Refer to FIR# 691200184 for complete fencing list for this facility. | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Kinzer 23-3B (API# 05-123-19415) has iron panel fencing. | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: | # | | |
| Comment: | Refer to FIR# 691200184 for complete equipment list for this facility. | | |
| Corrective Action: | | Date: | |

| | | | | | |
|-------------------------|--|----------|---------------------|---------|--------|
| Tanks and Berms: | | | | | |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| | | | CENTRALIZED BATTERY | | , |
| Comment: | This centralized battery serves 3 locations (330657, 330651, 330658). Refer to FIR# 691200184 for Tanks & Berms details. | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| Yes/No | NO | | |
|--------------------|----|--|-------|
| | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 251612 Type: WELL API Number: 123-19415 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well appears to SI and not producing. Production valves are closed both at the well and separator.

Corrective Action: _____ Date: _____

BradenHead

Comment: Bradenhead appears to be plumbed to surface.

Corrective Action: _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 691200187 | Site photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4477028 |