

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	The Qtr-Qtr of the Keiko 14-6 is SESW and the Qtr-Qtr of the Keiko 14-6 TR is SWSW on the lease signs. The Lot to the West is not a true 40 acres. I believe that the correct Qtr-Qtr for both wells is SESW. The footages also don't reflect this. The AS Drilled : Lat/Long on both well might reflect this.		
Corrective Action:	Pioneer needs to investigate and possibly correct the Lease sign on the Keiko 14-6 TR (05-071-8629) well to SESW. Contact (COGCC)Dennis Ahlstrand : 303-894-2100, xt 5116 of any changes.	Date:	06/30/2018

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type				corrective date
Progressive Cavity	# 2			
Comment:				
Corrective Action:			Date:	
Deadman # & Marked	# 10			
Comment:				
Corrective Action:			Date:	
Vertical Separator	# 2			
Comment:				
Corrective Action:			Date:	
Gas Meter Run	# 2			
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	No berm			
Corrective Action:	Tank needs berm around it.			Date: 06/30/2018

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 273233 Type: WELL API Number: 071-08150 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Facility ID: 281717 Type: WELL API Number: 071-08629 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
SEE : Sign/Markers : Qtr -Qtr on the Keiko 14-6 TR (05-071-08629) might not be correct and needs to be investigated. SEE : Tanks and Berms : No berm.	duranj	05/30/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687902081	Lease sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4477363
687902082	Lease sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4477364
687902083	Well pad	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4477365
687902084	Well pad	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4477366