

SHELL 697-34-14B
Api# 05-045-17584
Inspection # 689701392



Wellsite photo

SHELL 697-34-14B
Api# 05-045-17584
Inspection # 689701392



Unused equipment. Polypipe.

SHELL 697-34-14B
Api# 05-045-17584
Inspection # 689701392



Unused equipment. Out of service poly pipe.

SHELL 697-34-14B
Api# 05-045-17584
Inspection # 689701392



Unused equipment. Out of service poly pipe.



Unused equipment. Out of service poly pipe.

SHELL 697-34-14B
Api# 05-045-17584
Inspection # 689701392



Unused equipment. Out of service poly pipe. Cut off pipe is open ended.



Unused equipment. Out of service poly pipe.

SHELL 697-34-14B
Api# 05-045-17584
Inspection # 689701392



Unused dirt berm.

SHELL 697-34-14B
Api# 05-045-17584
Inspection # 689701392



Cover missing from heat unit on separator.



Cover missing from heat unit on separator.

SHELL 697-34-14B
Api# 05-045-17584
Inspection # 689701392



Vent turbine is off of separator unit.

SHELL 697-34-14B
Api# 05-045-17584
Inspection # 689701392



Erosion rill on lease road.

SHELL 697-34-14B
Api# 05-045-17584
Inspection # 689701392



Check dam above location.



Erosion rill from check over flow.