

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/23/2018

Submitted Date:

05/30/2018

Document Number:

688800110

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
313624 \_\_\_\_\_ Hughes, Jim \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46685  
Name of Operator: KINDER MORGAN CO2 CO LP  
Address: 1001 LOUISIANA ST SUITE 1000  
City: HOUSTON State: TX Zip: 77002

**Findings:**

- 6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
KinderMorgan		CO2Source_Regulatory@kindermorgan.com	<a href="#">SW Inspection Reports</a>
Roy, Catherine		catherine.roy@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295423	WELL	PR	10/17/2014	STRT	083-06649	Goodman Point 16	EI
313624	LOCATION	AC			-	GOLDMAN POINT (GP #16)-N37N17W 33NWNW	EI

**General Comment:**

On May 23, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Kinder Morgan GP-16 location as it relates to Remediation Project #9663. Area 145 Reclamation Specialist Catherine Roy and Kinder Morgan Representative Mike Hannigan were on site during this site visit. For the most recent field inspection report of this facility, please refer to document #680602691. Please refer to document #200439546 for more information regarding remediation efforts on this location. This inspection was conducted to determine the current surface condition of the area where the drilling pits existed.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign posted near location entrance.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 295423 Type: WELL API Number: 083-06649 Status: PR Insp. Status: EI

Facility ID: 313624 Type: LOCATION API Number: - Status: AC Insp. Status: EI

**Environmental**

**Spill/Remediation:**

Comment: [Please refer to REM Project #9663 in the COGIS database for more information.](#)

Corrective Action:  Date:

Emission Control Burner (ECB):

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>On May 23, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Kinder Morgan GP-16 location as it relates to Remediation Project #9663. Area 145 Reclamation Specialist Catherine Roy and Kinder Morgan Representative Mike Hannigan were on site during this site visit. For the most recent field inspection report of this facility, please refer to document #680602691. Please refer to document #200439546 for more information regarding remediation efforts on this location. This inspection was conducted to determine the current surface condition of the area where the drilling pits existed. Areas where EC and SAR exceed Table 910-1 standards were amended with gypsum in the fall of 2017.</p>	hughesj	05/30/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800111	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4477457">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4477457</a>