

**Inspection Photo
Couey 32-5 (D32)
API # 045-07630
Inspection # 689301222**



Location Photo #1



Location Photo #2

**Inspection Photo
Couey 32-5 (D32)
API # 045-07630
Inspection # 689301222**



**Location Photo #1, stained rock inside tank
battery containment**