

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/23/2018

Submitted Date:

05/30/2018

Document Number:

688800118

FIELD INSPECTION FORM

Loc ID 313602 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46685
Name of Operator: KINDER MORGAN CO2 CO LP
Address: 1001 LOUISIANA ST SUITE 1000
City: HOUSTON State: TX Zip: 77002

Findings:

- 7 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
KinderMorgan		CO2Source_Regulatory@kindermorgan.com	SW Inspection Reports
Roy, Catherine		catherine.roy@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279715	PIT	AC			-	MC8	EI
279717	WELL	PR	01/04/2007	STRT	083-06625	(MOQUI) MC 8	EI
313602	LOCATION	AC			-	(MOQUI) MC-N36N17W 6NWSW	EI

General Comment:

On May 23, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Kinder Morgan MC-8 location as it relates to Remediation Project #9886. Area 145 Reclamation Specialist Catherine Roy and Kinder Morgan Representative Mike Hannigan were on site during this site visit. For the most recent field inspection report of this facility, please refer to document #680602299. Please refer to document #200440460 for more information regarding remediation efforts on this location. This inspection was conducted to determine the current surface condition of the area where the drilling pits existed.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Location sign posted near entrance.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Stock panel enclosure.		
Corrective Action:		Date:	
Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 279715 Type: PIT API Number: - Status: AC Insp. Status: EI

Facility ID: 279717 Type: WELL API Number: 083-06625 Status: PR Insp. Status: EI

Facility ID: 313602 Type: LOCATION API Number: - Status: AC Insp. Status: EI

Environmental

Spill/Remediation:

Comment: [Please refer to REM Project #9886 in the COGIS database for more information.](#)

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Drilling Pit Lined: Pit ID: 279715 Lat: 37.404878 Long: -108.770417

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date:

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date: _____

COGCC Comments

Comment	User	Date
<p>On May 23, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Kinder Morgan MC-8 location as it relates to Remediation Project #9886. Area 145 Reclamation Specialist Catherine Roy and Kinder Morgan Representative Mike Hannigan were on site during this site visit. For the most recent field inspection report of this facility, please refer to document #680602299. Please refer to document #200440460 for more information regarding remediation efforts on this location. This inspection was conducted to determine the current surface condition of the area where the drilling pits existed. REM Project #9886 involved the application of soil amendments in the fall of 2017 to areas that had EC and SAR values exceeding Table 910-1 standards.</p>	hughesj	05/30/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800119	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4477913