

# Inspection Photos

Variance Request for Multiple Pit Locations

Operator: Kinder Morgan CO2 Co.

MC8

Date: 4/23/2018



**Photo 1. View of former pit area from the northwestern portion facing toward the center of the well pad. Former pit area is north of the well pad. Area in foreground is gypsum treated. Revegetation is largely comprised of smooth brome (*Bromus inermis*).**



**Photo 2. View of former pit area from the northwestern corner facing eastward.**



**Photo 3. View of another gypsum-treated portion of the former pit area in the northeastern portion.**



**Photo 4. View of reference area north of the project area facing northward.**