

Inspection Photos
Location Name: Spetter 5-8
API: 05-081-06548



Photo 1. Overview of location taken at entrance facing north.



Photo 2. Risers not marked for abandonment or LOTO.

Inspection Photos
Location Name: Spetter 5-8
API: 05-081-06548



Photo 3. Waddles installed improperly.



Photo 4. Waddles installed improperly.

Inspection Photos
Location Name: Spetter 5-8
API: 05-081-06548



Photo 5. Waddles installed improperly.



Photo 6. Tank labeled "out of service" stored on location.