

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/23/2018

Submitted Date:

05/30/2018

Document Number:

688800124**FIELD INSPECTION FORM**

Loc ID 313610	Inspector Name: Hughes, Jim	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____
------------------	--------------------------------	---	-------------------

**Operator Information:**

OGCC Operator Number: 46685

Name of Operator: KINDER MORGAN CO2 CO LP

Address: 1001 LOUISIANA ST SUITE 1000

City: HOUSTON State: TX Zip: 77002

**Status Summary:**

☐ THIS IS A FOLLOW UP INSPECTION

☒ FOLLOW UP INSPECTION REQUIRED

☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
KinderMorgan		CO2Source_Regulatory@kindermorgan.com	<a href="#">SW Inspection Reports</a>
Fischer, Alex		alex.fischer@state.co.us	
Roy, Catherine		catherine.roy@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293261	WELL	TA	03/06/2018	OW	083-06634	GOODMAN POINT 12	EI
313610	LOCATION	AC			-	GOODMAN POINT-N36N17W 6SESE	EI

**General Comment:**

On May 23, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Kinder Morgan GP-12 location as it relates to Remediation Project #9668. Area 145 Reclamation Specialist Catherine Roy and Kinder Morgan Representative Mike Hannigan were on site during this site visit. For the most recent field inspection report of this facility, please refer to document #680602284. Please refer to document #200439558 for more information regarding remediation efforts on this location. This inspection was conducted to determine the current surface condition of the area where the drilling pits existed.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign posted near location entrance.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Landowner water truck trailer and water stock tanks.		
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Stock panel enclosure.		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	293261	Type:	WELL	API Number:	083-06634	Status:	TA	Insp. Status:	EI
Facility ID:	313610	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	EI

## Environmental

### Spill/Remediation:

Comment: [Please refer to REM Project #9668 for more information.](#)

Corrective  
Action:

Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment:

Pilot: \_\_\_\_\_

Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On May 23, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Kinder Morgan GP-12 location as it relates to Remediation Project #9668. Area 145 Reclamation Specialist Catherine Roy and Kinder Morgan Representative Mike Hannigan were on site during this site visit. For the most recent field inspection report of this facility, please refer to document #680602284. Please refer to document #200439558 for more information regarding remediation efforts on this location. This inspection was conducted to determine the current surface condition of the area where the drilling pits existed.	hughesj	05/30/2018

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800125	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4478140">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4478140</a>