

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/23/2018

Submitted Date:

05/30/2018

Document Number:

688800126**FIELD INSPECTION FORM**

| | | | | |
|---|--------------------------------|---|-------------------|---|
| Loc ID 313616 | Inspector Name: Hughes, Jim | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ | Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED |
| Operator Information: OGCC Operator Number: <u>46685</u> Name of Operator: <u>KINDER MORGAN CO2 CO LP</u> Address: <u>1001 LOUISIANA ST SUITE 1000</u> City: <u>HOUSTON</u> State: <u>TX</u> Zip: <u>77002</u> | | | | Findings: <u>6</u> Number of Comments <u>0</u> Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested |

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|-------|---------------------------------------|---------------------------------------|
| KinderMorgan | | CO2Source_Regulatory@kindermorgan.com | SW Inspection Reports |
| Fischer, Alex | | alex.fischer@state.co.us | |
| Roy, Catherine | | catherine.roy@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|----------|--------|-------------|------------|-----------|--------------------------------------|-------------|
| 295002 | WELL | PR | 10/28/2009 | STRT | 083-06641 | GOODMAN POINT 15 | EI |
| 313616 | LOCATION | AC | | | - | GOODMAN POINT (GP#15)-N36N17W 18NWNE | EI |

General Comment:

On May 23, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Kinder Morgan GP-15 location as it relates to Remediation Project #9885. Area 145 Reclamation Specialist Catherine Roy and Kinder Morgan Representative Mike Hannigan were on site during this site visit. For the most recent field inspection report of this facility, please refer to document #680602294. Please refer to document #200440458 for more information regarding remediation efforts on this location. This inspection was conducted to determine the current surface condition of the area where the drilling pits existed.

Location**Lease Road:**

| | | | |
|-------------------|-------|-------|--|
| Type | Other | | |
| comment: | | | |
| Corrective Action | L | Date: | |

Overall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|-------------------------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Sign posted near location entrance. | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: Posted on location sign.

Corrective Action: Date:

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|----------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 295002 | Type: | WELL | API Number: | 083-06641 | Status: | PR | Insp. Status: | EI |
| | | | | | | | | | |
| Facility ID: | 313616 | Type: | LOCATION | API Number: | - | Status: | AC | Insp. Status: | EI |
| | | | | | | | | | |

Environmental

Spill/Remediation:

Comment: [Please refer to REM Project #9885 for more information.](#)

Corrective
Action:

Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____

Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|---|---------|------------|
| On May 23, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Kinder Morgan GP-15 location as it relates to Remediation Project #9885. Area 145 Reclamation Specialist Catherine Roy and Kinder Morgan Representative Mike Hannigan were on site during this site visit. For the most recent field inspection report of this facility, please refer to document #680602294. Please refer to document #200440458 for more information regarding remediation efforts on this location. This inspection was conducted to determine the current surface condition of the area where the drilling pits existed. | hughesj | 05/30/2018 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 688800127 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4478141 |