

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/29/2018

Submitted Date:

05/31/2018

Document Number:

688800130

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
320854 _____ Hughes, Jim _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: _____ 900 _____
 Name of Operator: ALAMOSA DRILLING INC _____
 Address: 8150 N. CENTRAL EXPY - STE 750 _____
 City: _____ DALLAS _____ State: _____ TX _____ Zip: _____ 75205- _____

Findings:

- _____ 12 Number of Comments
 _____ 2 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Moore, Todd	(214) 368-6700/ (719)342-1445	kiowagas@sbcglobal.net	All Inspections
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205242	WELL	SI	12/01/2017	OW	007-06120	CHAVEZ 1	EI

General Comment:

On May 29, 2018 COGCC SW EPS conducted a follow up environmental field inspection of the Alamosa Drilling Chavez #1. For the most recent field inspection report for this facility, please refer to document #688800073. Corrective actions required by that document have not been completed.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	Free standing sign near AST only lists Chavez #1 as contributing well.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Free standing sign near well head.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	AST has NFPA placard and is labeled with contents and capacity.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Posted on location signs.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Crude Oil	WELLHEAD	<= 1 bbl	
Comment:	Stained soil around well head.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Corrective action date taken from previous inspection report.		Date: <u>05/18/2018</u>
Crude Oil	Tank	<= 1 bbl	
Comment:	Stained soil below load out valve on AST.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Corrective action date taken from previous inspection report.		Date: <u>05/18/2018</u>
In Containment: No			
Comment:			
<input checked="" type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Hog wire enclosure around pump jack and well head.		
Corrective Action:		Date:	
Equipment:			
Type: Flow Line	# 1		corrective date
Comment:			

Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Supply shed.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		37.018081,-106.875100
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 205242 Type: WELL API Number: 007-06120 Status: SI Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On May 29, 2018 COGCC SW EPS conducted a follow up environmental field inspection of the Alamosa Drilling Chavez #1. For the most recent field inspection report for this facility, please refer to document #688800073. Corrective actions required by that document have not been completed.</p> <p>An area of approximately 4' by 7' around the well head is stained with oil. The well head is wet with oil. This issue was noted in the previous inspection. Corrective action date has been taken from that inspection report to document days of non-compliance. Repair leaking stuffing box, remove impacted soil, and provide COGCC EPS staff waste manifests for impacted material disposal.</p> <p>The area beneath the truck load out valve on the AST is stained with oil. This issue was noted in the previous inspection. Corrective action date has been taken from that inspection report to document days of non-compliance. Remove impacted soil and provide COGCC EPS staff with waste manifests for impacted material disposal.</p>	hughesj	05/31/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800131	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4478655