

Inspection Photos
Location Name: Nielson #3
API: 05-007-06116



Nielson #3 pump jack and well head.



Unused chemical injection system, noted in previous inspection report.

Inspection Photos
Location Name: Nielson #3
API: 05-007-06116



Stained soil around well head, noted in previous inspection report.



Well head is wet and surrounded by stained soil.

Inspection Photos
Location Name: Nielson #3
API: 05-007-06116



Stained soil beneath load out valve on AST. Tank is stained with oil, noted on previous inspection.



Stained soil beneath valve on AST.