



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern portion of the project area from the northwestern corner facing eastward. Revegetation is grazed and largely not in identifiable condition. Western wheatgrass was observed (*Pascopyrum smithii*).



Photo 3. View of the western portion of the project area from the northwestern corner facing southward.



Photo 4. View of musk thistles within the interim reclamation area. Approx. 100 individuals observed.



Photo 5. View of rilling along the pipeline alignment in the western project area.