

Inspection Photos
Location Name: PEOC-NVG 41-23H
API: 05-107-06173



Photo 1. Overflow and staining from gauge hatch.



Photo 2. Overflow and staining from pop-off valve.

Inspection Photos
Location Name: PEOC-NVG 41-23H
API: 05-107-06173



Photo 3. Soil staining in tank battery berm.



Photo 4. Soil staining in tank battery berm.

Inspection Photos
Location Name: PEOC-NVG 41-23H
API: 05-107-06173



Photo 5. Soil staining in tank battery berm.



Photo 6. Fresh gravel/soil at flowline at wellhead.

Inspection Photos
Location Name: PEOC-NVG 41-23H
API: 05-107-06173



Photo 7. Fresh gravel at wellhead.



Photo 8. Gravel stored on location.