

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/25/2018

Submitted Date:

05/25/2018

Document Number:

684905470

**FIELD INSPECTION FORM**

Loc ID 318942 Inspector Name: Pesicka, Conor On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 95620  
Name of Operator: WESTERN OPERATING COMPANY  
Address: 1165 DELAWARE STREET #200  
City: DENVER State: CO Zip: 80204

**Findings:**

- 14 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
James, Steve	(303) 893-2438	steve@westernoperating.com	<a href="#">All Inspections</a>
Leonard, Mike		mike.leonard@state.co.us	
Hart, Dale	(719) 729-3391	dalehartwoc@fairpoint.net	<a href="#">All Inspections</a>
Allison, Rick		rick.allison@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
111624	PIT	AC	09/23/1999		-	HOOZIE-BJOLIN 1	AC
242550	WELL	PR	02/02/2001	OW	123-10341	HOOZEE-BJOLIN 1	PR

**General Comment:**

[Followup inspection to inspection doc#684905316.](#)  
[Edit \(5/30/18\): Changed rule citation on F5 tab, pits, from 906 to 902.c.; on F2 tab, housekeeping, 907.f. to 907.A.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Incorrect sign at pump jack		
Corrective Action:	Install sign to comply with rule 210.b.	Date:	06/18/2018

**Emergency Contact Number:**

Comment:	Called number @ 1200hr. Received return call informing inspector that number was not to operator.		
Corrective Action:	Install sign to comply with rule 210.b.	Date:	05/18/2018

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained soil at engine		
Corrective Action:	Comply with rule 603.f. Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.	Date:	05/18/2018

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	barbed wire		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	barbed wire		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	containers- 1 propane		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	gas engine		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.536910,-103.642840
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 111624 Type: PIT API Number: - Status: AC Insp. Status: AC

Facility ID: 242550 Type: WELL API Number: 123-10341 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR intermittently.

Corrective Action:

Date:

**BradenHead**

Comment: Bradenhead not plumbed to surface.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: [Some possible stormwater issues on SW corner of location.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 111624 Lat: 40.536872 Long: -103.643533

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date: c

**Fencing:**

Fencing Type: \_\_\_\_\_ Fencing Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date: \_\_\_\_\_

**Netting:**

Netting Type: Mesh Netting Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: YES 2+ feet Freeboard: YES

Comment: [Oil slick on top of water](#)

Corrective Action [Remove oil from pit per Rule 902.c. Contact COGCC EPS staff.](#)  
[24 hr to remove fluids, 30 days to remove/remediate stained soil.](#) Date: 05/26/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401654508	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4475526">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4475526</a>
684905471	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4475520">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4475520</a>