

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/01/2018

Submitted Date:

06/01/2018

Document Number:

684905482**FIELD INSPECTION FORM**Loc ID 317532 Inspector Name: Pesicka, Conor On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 7800Name of Operator: BEREN CORPORATIONAddress: 2020 N BRAMBLEWOOD STREETCity: WICHITA State: KS Zip: 67206**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:19 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Reynolds, Rodney	(316) 337-8340	reynoldsr@berexco.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
100573	PIT	AC	09/23/1999		-	MOYER "A"	AC
100574	PIT	AC	09/23/1999		-	MOYER "A"	AC
100575	PIT	AC	09/23/1999		-	MOYER "A" 1	AC
239238	WELL	PR	07/29/2014	OW	123-07025	MOYER UNIT 14-29	PR
433344	TANK BATTERY	AC	04/14/2009		-	MOYER 'A'-612N56W 29SESW	AC

General Comment:[Followup inspection to doc#684903861. Was for facid#433329 prior.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	corrosion inhibitor		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Trash removed from loadout, pumps. Trash in separator house.		
Corrective Action:	comply with rule 603.f.	Date:	07/03/2017
Type	OTHER		
Comment:	Stained soil at valve fittings, around vessels, in treater house, see pictures.		
Corrective Action:	Comply with rule 603.f. Properly treat or dispose of oily waste in accordance with Rule 907.e. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	07/02/2018

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	cattle panel		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	cattle panel		

Corrective Action:		Date:	
Type	PIT		
Comment:	cattle panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	pumps- 3 corrosion inhibitor		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	injection pump		
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLS	FIBERGLASS AST		40.980460,-103.661030	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shared with produced waterp				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	400 BBLS	FIBERGLASS AST		40.980330,-103.661170	

Comment:		crude oil and water					
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:		Shared with crude oil					
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	5	300 BBLs	STEEL AST		40.980330,-103.661170		
Comment:		Stained soil at loadouts removed.					
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	6	300 BBLs	FIBERGLASS AST		40.980460,-103.661030		
Comment:							
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:						Date:	

Inspected FacilitiesFacility ID: 100573 Type: PIT API Number: - Status: AC Insp. Status: ACFacility ID: 100574 Type: PIT API Number: - Status: AC Insp. Status: ACFacility ID: 100575 Type: PIT API Number: - Status: AC Insp. Status: ACFacility ID: 239238 Type: WELL API Number: 123-07025 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadComment: Bradenhead plumbed to surface.

Corrective Action:

Date: _____

Facility ID: 433344 Type: TANK API Number: - Status: AC Insp. Status: AC

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Fail	Gravel	Pass			

Comment: Stormwater erosion on S side of location, between facility and pit.Corrective Action: Install or repair required BMPs per Rule 1002.f.Date: 07/02/2018**Pits:** ☐ NO SURFACE INDICATION OF PITType: Lined: NO Pit ID: 100575 Lat: 40.980183 Long: -103.660670

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective Action: _____

Date: c**Fencing:**

Fencing Type: _____ Fencing Condition: _____

Comment: _____

Corrective Action: _____

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Corrective Action: _____

Date: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: _____

Corrective Action: _____

Date: _____

Type: Lined: NO Pit ID: 100574 Lat: 40.979862 Long: -103.660615

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective Action: _____

Date: c**Fencing:**

Fencing Type: _____ Fencing Condition: _____

Comment: _____

Corrective Action: _____

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:				Date:
Corrective Action				
Anchor Trench Present:		Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>	
Comment:				Date:
Corrective Action				
Type:	Lined: <u>NO</u>	Pit ID: <u>100573</u>	Lat: <u>40.980121</u>	Long: <u>-103.661084</u>
Reference Point:	Other:	Length:	Width:	
<u>Lining:</u>				
Liner Type:		Liner Condition:		
Comment:				Date: <u>c</u>
Corrective Action				
<u>Fencing:</u>				
Fencing Type:		Fencing Condition:		
Comment:				Date:
Corrective Action				
<u>Netting:</u>				
Netting Type:		Netting Condition:		
Comment:				Date:
Corrective Action				
Anchor Trench Present:		Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>	
Comment:	<u>multiple produced water pits</u>			Date:
Corrective Action				

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
684905483	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4482058