



Photo 1. View of the project area from the southeastern corner facing center. Poor revegetation on western cut-slope needs stabilization.



Photo 2. View of the western portion of the project area from the southwestern corner facing northward. Approx. 100 musk thistles (*Carduus nutans*) from the 2018 growing season were observed. Thistles will need to be treated this year if rosettes observed. Seeds will remain viable for 10-15 years and therefore, subsequent monitoring and treatment will be needed.



Photo 4. View of erosional channel approximately 3 feet wide and up to 2 feet deep forming where concentrated stormwater flows off of the southern portion of the project area.



Photo 5. View of area in the southwestern portion of the project area that needs revegetation and stabilization.

