

Inspection Photos  
Location Name: State 1-15  
API: 05-107-06033



**Photo 1. Overview of location taken at entrance facing southeast.**



**Photo 2. Access road overgrown.**

Inspection Photos  
Location Name: State 1-15  
API: 05-107-06033



**Photo 3. Noxious weeds on access road. (Leafy Spurge, Houndstongue)**



**Photo 4. Noxious weeds on access road. (Dalmatian Toadflax)**



Inspection Photos  
Location Name: State 1-15  
API: 05-107-06033



**Photo 5. Noxious weeds on location.  
(Houndstongue)**



**Photo 6. Noxious weeds on location. (Leafy Spurge)**