



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern portion of the project area from the southeastern edge facing northward. Revegetation is progressing on flat areas, largely with grasses such as western wheatgrass (*Pascopyrum smithii*), intermediate wheatgrass (*Thinopyron intermedium*), and crested wheatgrass (*Agropyron cristatum*). Vegetation on cut-slope is sparse and needs monitoring and revegetation if cover is not increasing.



Photo 3. View of the western portion of the project area from the southwestern edge facing northward. Unused pipe needs to be removed.



Photo 4. View of erosional channel in the southern portion of the project area.



Photo 5. View of another erosional channel in the southern portion of the project area.



Photo 6. View of pipes in the northern project area that need to be removed.