

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/21/2018

Submitted Date:

05/30/2018

Document Number:

689801158

FIELD INSPECTION FORM

Loc ID 312987 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 33825
Name of Operator: GEOTECH PRODUCTION INC
Address: 7844 S ESPANA WAY
City: AURORA State: CO Zip: 80016-

Findings:

- 9 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
henderson, ralph	(303) 690-0921	hap7844@aol.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223186	WELL	PR	06/01/2016	GW	081-06548	SPETTER 5-8	PR

General Comment:

[Routine FIU follow-up inspection.](#)
[Follow up to inspection from 8/11/2017 document number 689800166. All corrective actions remain outstanding.](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	303-888-7373	Date:	
Corrective Action:			

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	2 - 1" and 2 - 2" steel risers observed at 40.66899, -107.52255 not marked for abandonment or locked out tagged out. Flowline risers not LO/TO or marked are considered unused equipment		
Corrective Action:	Comply with Rule 603.f .	Date:	05/31/2018
Type	UNUSED EQUIPMENT		
Comment:	Unlabeled tank from previous inspection has been labeled "out of service" identifying it as unused equipment stored on location.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/30/2018

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type:		#		corrective date
Horizontal Heated Separator		# 1		
Comment:	40.66917, -107.52279			
Corrective Action:			Date:	
Gas Meter Run		# 1		
Comment:	40.66917, -107.52279			
Corrective Action:			Date:	
Bird Protectors		#		
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 223186 Type: WELL API Number: 081-06548 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Fail					BMP not properly installed.

Comment: Waddles have been added to erosion areas observed in previous inspection. Waddles are not secured to surface, allowing gaps where sediment may continue to migrate off location.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 07/02/2018

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Follow up to inspection from 8/11/2017 document number 689800166. All corrective actions remain outstanding.	waldrone	05/30/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401657419	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4478147
689801168	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4478146