

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/05/2018

Submitted Date:

06/08/2018

Document Number:

690300279

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
Spencer, Stan _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202

Findings:

- 2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only
Johnson, Derek	970-285-2200	DSJ@Bry.com	
Lujan, Carlos		carlos.lujan@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

General Comment:

Pre water share inspection of Centrized E&P. Pit is full to capacity ~2ft of freeboard. Water is clear, odor free and has no free floating hydrocarbon sheen. Aerator is operating near west edge. Pit fenced with 6 ft, barbwire-topped, chainlink. No netting. Pit perimeter both within and outside fence is heavily overgrown with weeds, rabbit brush, and sage. Weed control is required.

3x80K bbl PW/condensate tanks are surrounded by 6 ft poly-lined, concrete SPCC. Tanks appear to be in good condition with no indications of leakage. 8x300bbl condensate tanks within poly-lined steel SPCC show no indications of leakage.

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690300280	Insp photos 6-5-18	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4488560